


# VOLVO PASSENGER SIDE 1



Coolant cap, tank  
secure level full

Clamps secure

Engine no leaks

Hoses no  
cut/crack leak

Turbo, manifold  
exhaust no  
crack/leak

Fan blades, no  
cut/crack

Radiator no leak  
crack secure

Air line no  
cut, crack  
secure


Shock secure  
no leaks

Frame no  
crack bend

Ubolt, Leaf  
spring, Axle, Tie  
rod no crack bend  
secure

Tire no  
cut, crack, 3mm  
tread, even  
wear, proper

# VOLVO DRIVER SIDE1



**Engine No Leaks**

engine warm  
when cold check  
for oil level full

Compressor  
secure no  
crack

**Fan  
Blades**

Alternator


Cap

Steering  
tank, cap  
secure

Belt no  
cut/crack

Steering rod,  
no crack bend

# VOLVO DRIVER SIDE 2



# VOLVO DRIVER SIDE3

