

IN CAB INSPECTION

- Checking warning lights.
- Four-way flashers working.
- Dash lights working.
- High beam indicator working.
- Oil pressure in normal range.
- Coolant range is normal.
- Battery voltage in normal range.
- Enough fuel for the trip.
- Primary and secondary tank range is between 105 psi to 135 psi.
- Defroster working.
- Seat secure and adjusted for me
- Seatbelt secure no cuts or twists, could you please check yours.
- Steering wheel minimal play and adjusted for me.
- City and highway horns working.
- Both side windows clean, no cracks, rolls up and down.
- Both sideview mirrors clean, no cracks and adjusted for me.
- Windshield no cracks and clean.
- Wipers and washer fluid working.
- Papers (RIP) registration, insurance and pre-trip sheet are in back of my seat.